



State of Utah  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor

Ted Stewart  
Executive Director

James W. Carter  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340  
801-359-3940 (Fax)  
801-538-5319 (TDD)

July 2, 1996

Bill Hamm  
Idaho Quartzite Company  
P.O. Box 88  
Declo, Idaho 83323

Re: Notice of File Closure for Small Mining Activities, Dove Pass Quarry, S/003/019, Box Elder County, Utah

Dear Mr. Hamm:

This letter is to notify you that file #S/003/019, for the Dove Pass Quarry project, located in Box Elder County, Utah, will be retired from our files. On June 26, 1996, Lynn Kunzler of the Division recently inspected the project area and found the surface reclamation satisfactory (inspection memo enclosed).

If you have any questions or concerns regarding this action, please notify us within 15 days from receipt of this letter. Thank you for your time and consideration in completing the required reclamation on this project.

Sincerely,

D. Wayne Hedberg  
Permit Supervisor  
Minerals Regulatory Program

jb  
Enclosure  
cc: John Blake, SITLA  
S003019.cls





# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt  
Governor

Ted Stewart  
Executive Director

James W. Carter  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340  
801-359-3940 (Fax)  
801-538-5319 (TDD)

July 2, 1996

TO: Minerals File

FROM: Lynn Kunzler, Senior Reclamation Specialist *LK*

RE: Site Inspection, Dove Pass Quarry, S/003/019, Box Elder County, Utah

Date of Inspection: June 26, 1996  
Time of Inspection: 2:00 pm.  
Conditions: cloudy and windy  
Participants: Lynn Kunzler, DOGM

Purpose of Inspection: To inspect for final closure.

This quarry is located south of the Dove Pass on the Lynn road. Mr. Bill Hamm had requested that this file be closed on the annual report, since he no longer had the surface lease and was no longer interested in this site. This inspection found that about 0.1 acres had been disturbed, most of which has revegetated by natural invasion. The access road was difficult to find in places due to the amount of vegetation present. While a small area could be regraded, access by equipment to do so would disturb more area than what would be gained. It is therefore recommended that this file be closed.

Several photos were taken to document the site.

cc: Bill Hamm, Operator  
S003019.ins

